

APPENDIX - VIII

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.

No. 276/MP/B/2023

Date: 03-04-2023

It is certified that an inspection team headed by VIKAS KUMAR
EXECUTIVE OFFICER (Name of Officers
with designation) from NAGAR PALIKA PARISHAD (Name of
Department/Office) inspected the DAYAVATI DHARMAVIRA
PUBLIC SCHOOL BIJNOR (Name & Address of
the School) on _____ and found that the DAYAVATI DHARAVIRA
PUBLIC SCHOOL BIJNOR (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of ONE YEAR

Signature with Seal : _____
03/04/2023

Name : VIKAS KUMAR अधिकारी

Designation : EXECUTIVE OFFICER नगर पालिका परिषद
बिजनौर

NAGAR PALIKA PARISHAD
BIJNOR

To
DAYAVATI DHARMAVIRA PUBLIC SCHOOL
BIJNOR

OPP. INDIRA PARK, MEERUT ROAD, BIJNOR

(Name & Address of the Institution)

Principal
DAYAVATI DHARMAVIRA PUBLIC SCHOOL
SENIOR SECONDARY
BIJNOR
81075/2130259

Manager
Dayavati Dharmavira Public School
(Senior Secondary)
BIJNOR-246701 (U.P.)

कार्यालय अधिशासी अभियन्ता निर्माण खण्ड, उ०प्र० जल निगम
लडापुरा जलकल प्रांगण, झालू रोड, बिजनौर
(जल परीक्षण रिपोर्ट)

सेवा में:-

प्रधानाचार्य
डी०डी०पी०एस० बिजनौर

प्रयोगशाला पत्रिका का सन्दर्भ: 293

जल परीक्षण / 18

दिनांक:- 03.04.2023

क्र०स०	ग्राम/नगर/लोकेशन	स्रोत	टी०डी० एस० (पी०पी०एम०)	पी० एच०	टर्बिडिटी	रसायनिक परीक्षण पी०पी०एम० में						
						क्लोराइड	सम्पूर्ण कठोरता	सल्फेट	आयरन	नाइट्रेट	एल्केनिटी	टिप्पणी
1	डी०डी०पी०एस० बिजनौर	समरसिबल	169.5	7.652	0.56	10.95	132	8.86	0.14	8.56	130	संतोषजनक

नोट:-
1 मानको के लिये पृष्ठ दो का सन्दर्भ लें।
2 आयरन विश्लेषण हेतु नमूने एसिडिक में भेजे।

प्रतिहस्ताक्षरित

कैमिस्ट

जूनियर इंजी०

सहायक अभियन्ता
DAYAVATI DHARMAVIRA PUBLIC SCHOOL
SENIOR SECONDARY
BIJNOR
81075/2130259

Manager
Dayavati Dharmavira Public School
(Senior Secondary)
BIJNOR-246701 (U.P.)